



U.S. ARMY CORPS
OF ENGINEERS

FEATHER RIVER *Fact Sheet*

PL84-99 Sites

Emergency Levee Repairs

Location

River: Feather

Site Identification #:
20051230-025-002
(River Mile 19.4)

Latitude/Longitude:
39.018639/-121.589417

Nearest Impact Area:
Plumas Lake

County: Yuba

Bank: Left

Type of Damage

Bank erosion

Total Length of Repair


100 feet (approximate)

Repair Type

Relief wells

Lead Agency

Reclamation District 784



**For further information,
please contact:**

Les Schmittner
Project Manager
U.S. Army Corps of Engineers
(916) 440-2263

Lester.C.Schmittner@spk01.usace.army.mil